

Published based on [Honda Recalls Accord In US](#)

Honda Recalls Accord In US



Honda is recalling certain model year 2010-2011 Honda Accord V6 and model year 2011 Honda Pilot vehicles. The bolts that attach the lower left and right front damper bracket to the front suspension and the spindle nuts on the pilot may not have been properly tightened which may result in loss of steering. The spindle nuts for the axle on the accord v6 may not have been tightened properly which may result in excessive noise and/or loss of steering. Loss of steering increases the risk of a crash. Dealer will inspect and replace any loose front damper bracket bolts or spindle nuts on the pilot if necessary. Dealer will inspect and replace the spindle nuts on the Accord V6 if necessary.

You can also find this article published on [Honda Recalls Accord In US](#), and on the tag pages [Honda Accord](#).