

Published based on [Ferrari Recalls 458 Italia](#)

Ferrari Recalls 458 Italia



Ferrari has officially issued a recall of its latest supercar the 458 Italia for cases of engine fire (four reported till date). An adhesive used to attach a heat shield under the rear fender can ignite under high temperatures, leading to a larger fire in the engine bay. Ferrari has designed a new heat shield that attaches with rivets, negating the need for the adhesive. Owners of the 458 need to contact their dealers to get the problem sorted out for free.

You can also find this article published on [Ferrari Recalls 458 Italia](#), and on the tag pages [Ferrari 458](#).