

Published based on [Honda India Recalls 8532 Units Of 2007 City](#)

Honda India Recalls 8532 Units Of 2007 City



Honda India has announced recall of 8,532 units of 2nd Generation City, manufactured in 2007, for part replacement of Power Window Switch. The replacement would be carried out free of cost and the company will communicate directly with the [City ZX](#) owners, covered under this part replacement. The company will replace the part in these vehicles related to the problem of smoke coming out from the Power Window Switch if water enters the driver window.

You can also find this article published on [Honda India Recalls 8532 Units Of 2007 City](#), and on the tag pages [Honda City](#).