

Published based on [Nissan Recalls 5,39,864 Vehicles Worldwide](#)

Nissan Recalls 5,39,864 Vehicles Worldwide



Nissan has announced recalls to inspect and, if necessary, repair brake pedal pins and fuel-gauge components on certain trucks and minivans. These recall campaigns involve a total of 539,864 vehicles, a majority of which are in the United States. The recall affects 2005 through 2008 Nissan Titan, Armada and Infiniti QX56s as well as [Nissan](#) Frontier pickups and Pathfinder and Xterra SUVs produced between January and March 2006 and between October 2007 and January 2008.

There have been three reported instances of brake pedal pins partially disengaging, causing a loss of normal braking ability, and Nissan has determined that a manufacturing error on the part of the supplier is at the root of this issue. Unrelated to the brake-pin issue, vehicles at higher mileage levels may have fuel gauges which incorrectly indicate the amount of fuel in the tank. This may result in the vehicle running out of fuel while the gauge reads greater than empty. All vehicles currently on sale are free of the above problems.

You can also find this article published on [Nissan Recalls 5,39,864 Vehicles Worldwide](#), and on the tag pages [Nissan](#).